	Туре	L #	Hits	Search Text	DBs	Time Stamp	C o m m e n t s	ErrorDefinitio
1	BRS	L1	0	ATV same tire same chamfer	USPAT; EPO; JPO; DERWEN	2004/05/09 07:31		n
2	BRS	L2	106	tire same chamfer	USPAT; EPO; JPO; DERWEN T	2004/05/09 07:31		
3	BRS	L3	63	tire with chamfer	USPAT; EPO; JPO; DERWEN T	2004/05/09 07:31		
4	BRS	L4	18	tire same block with chamfer	USPAT; EPO; JPO; DERWEN T	2004/05/09		
5	BRS	L5	1	"6123129".PN.	USPAT	2004/05/09 07:35		
6	BRS	L6	0	<b>:</b>	USPAT; EPO; JPO; DERWEN T	2004/05/09 08:29		
7	BRS	L7	168	152/209.15	USPAT; EPO; JPO; DERWEN T	2004/05/09 08:55		

	Туре	L #	Hits	Search Text	DBs	Time Stamp	C o m m e n t s	E r r o r D e f i n i t i o
8	BRS	L8	266	152/209.22	USPAT; EPO; JPO; DERWEN T	2004/05/09 08:55		n
9	BRS	L9	729	152/209.28	USPAT; EPO; JPO; DERWEN T	2004/05/09 08:55		
10	BRS	L10	139	152/209.3	USPAT; EPO; JPO; DERWEN T	2004/05/09 08:55		
11	BRS	L11	574	152/000	USPAT; EPO; JPO; DERWEN T	2004/05/09		
12	BRS	L12	378	156/110.1		2004/05/09 08:55		
13	BRS	L13	583	703/1		2004/05/09 08:56		

	Туре	L#	Hits	Search Text	DBs	Time Stamp	C o m m e n t s	E r r o r D e f i n i t i o
14	BRS	L14	743	703/6	USPAT; EPO; JPO; DERWEN T	2004/05/09 08:56		n
15	BRS	L15	284	703/8		2004/05/09 08:56		

	Тур	L #	Hi	Search Text	DBs	Time Stamp	C o m m e n t s	f i n i t i	Err
1	BRS	L1	0	tire same lblock same "land ratio"		2004/05/09 10:23		n	0
2	BRS	L2		tire same block same "land ratio"	USPAT; EPO; JPO; DERWEN T	2004/05/09 10:42			0
3	BRS	L5		tire same block same (oblique or deviation) same chamfer	USPAT; EPO; JPO; DERWEN T	2004/05/09			0
4	BRS	L3	71	tire same block same (oblique or deviation)	USPAT; EPO; JPO; DERWEN T	2004/05/09 10:43			0

可以1000年 1000年 1